

Cruzer Enterprise Release Notes

Version 2.0.3, Build 16

May 2007

Cruzer Enterprise is a high-performance USB Flash Drive with enhanced security and management features. Cruzer Enterprise includes a protected read-only partition, a protected hidden partition, and a user accessible protected read/write partition. Enhanced management functionality is available through Cruzer Enterprise CMC.

Cruzer Enterprise supports Windows 2000 SP4, Windows XP Home SP1 and SP2, Windows XP Pro SP1 and SP2, Windows XP SP1 64-bit, Windows Server 2003 Standard Edition, Windows Server 2003 Enterprise Edition, and Vista.

This release includes the initial launch of the Cruzer Enterprise drive product.

Availability

Cruzer Enterprise is now readily available

Known Issues

Cruzer Enterprise 2.0.3, Build 16 release contains the following known issues:

Description	Recommended Workaround
Non-administrator user can receive "not enough free drive letters" when the first 2 free drive letters are not contiguous. [6114]	Manually remap drives to leave 2 free drive letters immediately after hard drives and optical drives. This will be fixed in a future release.
Administrator user format in Vista behaves the same as non-administrator format: the user must enter a password to enable the format.	N/A
After the computer is unlocked after standby or hibernate, the tray application is still running and the temporary folder is not removed	Reinsert the device before or during hibernation. When the computer comes back up, the user will need to login.
When the host PC is offline, trying to access online support generates a standard "the page cannot be displayed" message instead of a more informative custom message.	Online support can only be accessed when the PC is online.
In Windows 2000 SP4, the removable drive stays as <i>Unnamed Drive</i> after login [5381]	N/A
In Windows XP Home edition SP2, non-administrator user, the Cruzer Enterprise icon does not appear next to the CD partition in My Computer	N/A
In Windows XP or 2003 Server, clicking mouse while formatting stops Progress bar until format is complete.	N/A

Description	Recommended Workaround
ReadyBoost does not function properly in Vista.	N/A

SanDisk® Corporation general policy does not recommend the use of its products in life support applications where in a failure or malfunction of the product may directly threaten life or injury. Per SanDisk Terms and Conditions of Sale, the user of SanDisk products in life support applications assumes all risk of such use and indemnifies SanDisk against all damages. See “Disclaimer of Liability.”

This document is for information use only and is subject to change without prior notice. SanDisk Corporation assumes no responsibility for any errors that may appear in this document, nor for incidental or consequential damages resulting from the furnishing, performance or use of this material. No part of this document may be reproduced, transmitted, transcribed, stored in a retrievable manner or translated into any language or computer language, in any form or by any means, electronic, mechanical, magnetic, optical, chemical, manual or otherwise, without the prior written consent of an officer of SanDisk Corporation.

All parts of the SanDisk documentation are protected by copyright law and all rights are reserved.

SanDisk and the SanDisk logo are registered trademarks of SanDisk Corporation. CompactFlash is a U.S. registered trademark of SanDisk Corporation.

Product names mentioned herein are for identification purposes only and may be trademarks and/or registered trademarks of their respective companies.

© 2007 SanDisk Corporation. All rights reserved.

SanDisk products are covered or licensed under one or more of the following U.S. Patent Nos. 5,070,032; 5,095,344; 5,168,465; 5,172,338; 5,198,380; 5,200,959; 5,268,318; 5,268,870; 5,272,669; 5,418,752; 5,602,987. Other U.S. and foreign patents awarded and pending.

Lit. No. RN-CRE-0507-05 Rev. 1.0 05/07 Printed in U.S.A.

Revision History

May 2007 Revision 1.0—initial release